

Fig. 1





Fig. 2

*Fig. 3*




Fig. 4A





Fig. 4B

FOR "50" 5235/350

*Fig. 5*

240

New Inspection Inspection Info Comments

248 → INSPECTION INFO

242

- 1 Customer Name
- 2 Customer Phone
- 3 Customer Address
- 4 Customer City
- 5 Customer State
- 6 Customer Zip 246
- 7 Inspector Name
- 8 Inspection Date
- 9 Comments

244

| | |
|-------------------|--------------|
| Customer Name: | Bob Smith |
| Customer Phone: | 555-1212 |
| Customer Address: | 123 Main St. |
| Customer City: | Seattle |
| Customer State: | |
| Customer Zip: | |
| Inspector Name: | |
| Inspection Date: | |
| Comments: | |

Fig. 6

260

270 → INSPECTION INFO

Page Up ▲

- 1 Customer Name
- 2 Customer Phone
- 3 Customer Address
- 4 Customer City
- 5 Customer State
- 6 Customer Zip 272
- 7 Inspector Name
- 8 Inspection Date
- 9 Comments

Page Down ▼

264

262 268 266

New Inspection Inspection Info

Fig. 7




Fig. 8

09879829-06.1.01

308

| |
|---|
| <i>JOHN</i> INVENTORY PARTS ASSEMBLE INTAKE LUBRICATE CORE |
| <i>JAMIE</i> LUBRICATE CORE INSTALL INTAKE VERIFY CHARGE |
| <i>MAX</i> LUBRICATE CORE INSTALL INTAKE VERIFY CHARGE |
| <i>CAROL</i> INSTALL INTAKE VERIFY CHARGE RUN DIAGNOSTICS |
| INVENTORY ASSEMBLE LUBRICATE INSTALL VERIFY RUN |

Fig. 9

09879829 106 1101